

Inspection Report

Date Period:	9/7/26	to	9/11/26
Address:	Talus Subdivision		
Inspector:	Ryan Sheeran		
On Site Rep:	Jose De La Cruz		

Summary/Notes:	
Lot 4: Waiting on electrical parts before final Lot 5: Sold, working on interior finishes Lot 6: Will be finished as a spec home, interior finishes in progress Lot 9,11: Second floor framing in progress Lot 10,12,13,19,23: Occupied	

Pictures / Progress / Problems	
	

Pictures / Progress / Problems	
	

Summary of Week Activities	
Monday	
Tuesday	
Wednesday	
Thursday	
Friday	