

Inspection Report

Date Period:	10/12/26	to	10/16/26
Address:	Talus Subdivision		
Inspector:	Ryan Sheeran		
On Site Rep:	Jose De La Cruz		

Summary/Notes:	
Lot 9,11: Pick up framing in progress, gutters installed Lot 4: Final inspection complete Payment for issuance of new permits was submitted this week for lots 18,20, and 14. Lot 14 is sold. .	

Pictures / Progress / Problems	
	

Pictures / Progress / Problems	
	

Summary of Week Activities	
Monday	10/12/26
Lot 9 and 11: Roof nail inspection passed and shear nail inspection passed; performed by CSG. Lot 4: Final inspection passed; performed by CSG.	
Tuesday	
Wednesday	
Thursday	
Friday	