

Inspection Report

Date Period:	10/19/26	to	10/23/26
Address:	Talus Subdivision		
Inspector:	Ryan Sheeran		
On Site Rep:	Jose De La Cruz		

Summary/Notes:	
Lot 9,11: Sheet metal work on exterior; scaffolding set up; windows and doors have arrived; roof underlayment in place; plumbers start next week Lot 5,6: Waiting for cabinets to arrive Lot 14,15: Surveyors onsite friday Lot 9,11: Surveyors completed roof height verification	

Pictures / Progress / Problems	
	

Pictures / Progress / Problems	
	

Summary of Week Activities	
Monday	
Tuesday	
Wednesday	
Thursday	
Friday	