# Inspection Report

| | |
|---|---|
| **Date Period:** | 10/26/26 to 10/30/26 |
| **Address:** | Talus Subdivision |
| **Inspector:** | Ryan Sheeran |
| **On Site Rep:** | Jose De La Cruz |

| **Summary/Notes:** |
|---|
| Lot 9,11: Window installation in progress; framers doing pick up work<br><br>Lot 14: Preparation for work in progress, selections are being made for finishes<br><br>Lot 4: Working on plans for backyard landscaping<br><br>. |

**Pictures / Progress / Problems**





**Pictures / Progress / Problems**



## Summary of Week Activities

**Monday**

**Tuesday**

**Wednesday**

**Thursday**

**Friday**